SURFBOARD DING REPAIR ESTIMATES

Prices vary upon the size of ding, extent of damage and materials involve such as Poly Resin, Epoxy Resin, Cloth, Paint, etc. * MINIMUM REPAIR \$20.

Resin, Cloth, Paint, etc. A WINIMUM	REPAIR \$20.	PEQUEÑO (MENOR A 1")	GRANDE (MAYOR A 1")
	NOSE DING	\$ 35	\$ 50
	TRASHED NOSE	\$ 50	\$ 65
	BROKEN NOSE (UP TO 12')	\$ 150	
	Indeptit (The Angel (BAC) Section Section (1) (BAC) And (BAC) Section (1	\$ 100	
	BUCKLED NOSE (STRINGER INTACT)	\$ 110	
	(OTKINOLIK IIVIAOT)		
	RAIL DINGS	\$ 35	\$ 50
	DECK/BOTTOM HOLES/GASHES	\$ 20 \$ 35	
0	a. Crack not to foamb. S (Pequeño c/relleno)		
	c. L (Grande)	\$ 50	
		ONE SIDE	ONE SIDE
	BUCKLED BOARDS (ROCKER INTACT)	(PU)	(EP or PAINT)
	> SHORTBOARD > LONGBOARD	\$ 110	\$ 135
	> LONGBOARD	\$ 120	\$ 145
	BROKEN BOARDS	IF THE BOARD HAS BEEN BROKEN,	
	> SHORTBOARD	THE CLIENT MUST PAY	THE ESTIMATED
	> LONGBOARD	VALUE OF THE BOARD.	
100	RIPPED/TORN GLASS	\$ 40 PER FOOT	
(大)			
	DELAMINATION		
and a property of the second	(DEPENDING ON SEVERITY)	\$ 50 PER FOOT	
	FIN REPAIR		
	> GLASSED ON	\$ 100	
3)- T	> FCS = ONE PLUG, or TWO PLUGS	\$ 85	
•	> FUTURE	\$ 85	
	> LONGBOARD FIN BOX	\$ 85	
•	TAIL DINGS		A 405
300	> BROKEN TAIL (UP TO 12')	\$ 90	\$ 135
10 10	> FLAT AREA > CORNERS	\$ 30 \$ 35	\$ 50
	> TRASHED	\$ 50	\$ 70
	> LEASH PLUG	\$ 35	i

NOTE: EPOXY BOARD repair will be EXTRA DUE TO THE MUCH HIGHER COST OF EPOXY RESIN. RUSH ORDERS OF 2 - 3 DAYS AVAILABLE FOR AN ADDITIONAL CHARGE OF \$30 - \$50 BASED ON WORK INVOLVED AND SEVERETY OF DAMAGE. PAINTED BOARDS + 30%